## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	i de la composition de la composition La composition de la
	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	
and the second of the second of the second	the second secon
NEVER HOOK	ED UP.
and the second of the second o	A TOTAL CONTROL OF THE STATE OF
	the second of
SIGNED	FILED AT ENGINEER'S OFFICE
Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	The second secon

## Nº 8619

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON	, оню, <i>Т.с.</i>	huary 8	
RECEIVED OF ACA	ulaun	, 	FEE OF	s 2
FOR WHICH PERMISSION IS GRANTED				
TO TAP Sanstary				
of 1, 12.6. T				
THE PREMISES BEING LOT NO. $318$			7	
WORK TO BE DONE IN ACCORDANCE WITH ORI	•			
OF THE DEPARTMENT OF PUBLIC SERVICE.				
Land Malde	der come			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.