

11-4'

No 8620

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 2-13-23

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 831

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 4"



WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

G. HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

[Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Roots 6' of Pipe

Repair
N^o 8620

2 55
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Feb. 12*

RECEIVED OF *Kalshauer* FEE OF \$ *2*

FOR WHICH PERMISSION IS GRANTED *Wm Lynn Smith*

TO TAP *Sanitary* SEWER ON THE *West*

OF *W. L. D. W.* AVE. ST. TYPE OF STREET *Chipp & Laid*

THE PREMISES BEING LOT NO. *3320*, HOUSE NO. *831*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Kalshauer*

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.