

19-23

N<sup>o</sup> 8636

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-31-73

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM STUB in MT 9' OF

HOUSE NO. 2028

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR BEAUCY EXCA.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED L. Latham  
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N<sup>o</sup> 8636

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS  
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 28

RECEIVED OF Meadows Plaza - Bee Lee FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

TO TAP Sanitary SEWER ON THE North

OF Lincoln Way East AVE. ST. TYPE OF STREET

THE PREMISES BEING LOT NO. O.L. 330 HOUSE NO. 2028 - Bee

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Beaver Excavating

**Note:** This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.