

✓
Nº 8642

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

4-11-73?

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

?

HOUSE NO.

509

SIZE OF PIPE USED

6" ?

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

?

WAS LATERAL AT Prop

yes


WAS ATTACHED TO MAIN

NO

NAME OF CONTRACTOR

J. GLICK & A. DIAI

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

LATERAL covered Did NOT CALL

N^o 8642

18
1880

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, April 6

RECEIVED OF Jacob Chick FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED John Hardisty

TO TAP Sanitary SEWER ON THE Front

OF East Ave. T. E. AVE. ST. TYPE OF STREET Chippewa

THE PREMISES BEING LOT NO. 17566, HOUSE NO. 509

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR David

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**