

19-
✓
N^o 8646

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

4-15-73

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

wye 125' SE. of MH

HOUSE NO.

2410

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

No

WAS ATTACHED TO MAIN


Yes

NAME OF CONTRACTOR

M. GERTSEN SLAGER

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



SIGNED

J. Satham
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8646

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, APRIL 27

RECEIVED OF MIKE GERSTENSLAGER FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED MIKE GERSTENSLAGER

TO TAP SAN SEWER ON THE NORTH

OF LUGAN TRAIL N.E. AVE. ST. TYPE OF STREET CURB CUT

THE PREMISES BEING LOT NO. 13599, HOUSE NO. 2410

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR MIKE GERSTENSLAGER

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.