## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-7-73	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED  POR WAS LATERAL AT BURB?	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 4.5 Sout 14 of 14 9 y
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
N. ———	50
.•	3/28
SIGNED dartage	FILED AT ENGINEER'S OFFICE
Inspector for City	··

**№** 8649

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

