№ 8659

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $8-2-73$ HOUSE NO. 1067 SIZE OF PIPE USED $6''$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH.
WAS LATERAL AT CURB? NO	NAME OF CONTRACTOR 6, HOLDIER 134 WM
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
+ + + + + + + + + + + + + + + + + + +	7038 BAND
	g b
SIGNED / Washinspector for City	1PPO FILED-AT-ENGINEER'S-OFFICE 30"
REMARKS	

№ 8659

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

,	MASSILLON, OHIO, June 15
RECEIVED OF Haldubaum	FEE OF \$ 25
FOR WHICH PERMISSION IS GRANTED Danse	
	WER ON THE South
of Silfo Rend 716. AVE. TY	
THE PREMISES BEING LOT NO. 10 49 11 4 P.A. 16	/ /
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	D. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR Addidan	
NAME OF CONTRACTOR THE CONTRACTOR	<i></i>

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.