FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $\frac{5/3}{3}/73$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 733	
/ +*	PISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT
SIZE OF PIPE USED	CURB LINE AND DEPTH 127 - 7½ D
WAS LATERAL AT CURB? YES	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR 1/5 W CONTRACTORS
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	ALL OF BUILDING SERVED.
100	23½' 123½' 123½' 127' 127' 127'
SIGNED JIME THINK Inspector for City	FILED AT ENGINEER'S OFFICE
mapecial for Oily	
•	

Kepain 1º 8675

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	equit 9
RECEIVED OF D. B. Daugla	<u>s</u>	FEE OF \$ 25
for which permission is granted NBA	Jauglas	***************************************
TO TAP Samilary SEV	VER ON THE 7/2	est
OF Dienfuld Pane V.E. AVE. TYP	PE OF STREET Chip	& seel
THE PREMISES BEING LOT NO. 12433	, HOUSE NO	733
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.	. 19-1971 DULY PASSED F	BY THE CITY COUNCIL, AND

IAME OF CONTRACTOR A. & W. Cantractus

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.