

N^o 8697

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-29-73

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2425

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH



WAS LATERAL AT CURB? Yes

Iron

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR G MALAVITE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED L. Latham
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8697

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, Lot 23

RECEIVED OF Paul Kerner

FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED Paul Kerner

TO TAP Sanitary

SEWER ON THE East

OF Franklin St. N.E.

AVE.
ST.

TYPE OF STREET City & Loc

THE PREMISES BEING LOT NO. 13580

HOUSE NO. 2475

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR M. J. Kerner

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**