**№** 8698

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 24 35	DISTANCE FROM FIRST MANHOLE  DOWN-STREAM  DISTANCE FROM FIRST MANHOLE  DOWN-STREAM TO DITCH AT 75' WESTOFM 8'DEP  CURB LINE AND DEPTH
WAS LATERAL AT CURB? Y 5	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR MALAVITE
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
	100 8 450 B 453 450 B
SIGNED William Hammer	EU ED ART ENGINEERING GEFIGE
Inspector for City	FILED AT ENGINEER'S OFFICE

Nº 8698

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

<i>a</i>	MASSILLON, OHIO,	23
RECEIVED OF Paul Ka	<i>2</i> *	FEE OF \$ 25
FOR WHICH PERMISSION IS GRANTED Paul	Konniky	
to tap Sanctair se		ZA.
of Tanglin of 16 AVE.	,	E.C.
THE PREMISES BEING LOT NO. 13591		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N		
OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR MANERE	; , ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
•		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.