## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 1-6-	7 4 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	~	
SIZE OF PIPE USED  WAS LATERAL ATTOURE?  Ve	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CORB LINE AND DEPTH	60' NIOSM	8/210
WAS ATTACHED TO MAIN	A NAME OF CONTRACTOR	G. MALA	* VITE
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.	,	70
			30°874 8721
SIGNED Inspe	cotor for City FILED AT	ENGINEER'S OFFICE	
REMARKS		·	~~~~~~ <del>~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~</del>

## Nº 8715

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

· · · · · · · · · · · · · · · · · · ·	MASSILLON, OHIO, Lan. 3			
RECEIVED OF Tand Man	ansley FEE OF \$ 1=			
FOR WHICH PERMISSION IS GRANTED SALE	Kohamby			
TO TAP Samulary SE	WER ON THE			
of Tanganer Lie II is ST. TY				
THE PREMISES BEING LOT NO. 13035	, HOUSE NO			
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR 2/1/alancter	·			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.