

9-8
N^o 8718

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

2-28-74

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

10' EAST OF MH 9'6" DEEP

HOUSE NO.

2640

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

No

WAS ATTACHED TO MAIN


YES

NAME OF CONTRACTOR

ALBRECHT BROS.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
↑



SIGNED

William Hammer

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

OFFICE OF THE DIRECTOR OF PUBLIC SEI

PERMIT TO TAP SEWER

MASSILLON, OHIO.

RECEIVED OF

FEE OF \$ 4.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER ON THE

OF

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.