## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-/3-/	IF SO HOW AND LO			· ·
HOUSE NO	DISTANCE FROM FI			
SIZE OF PIPE USED	CURB LINE AND DI	EPTH 5-9	NorTHOS	LPSTVEAM
WAS LATERAL AT CURB? YES	<del></del>			
WAS ATTACHED TO MAIN	NAME OF CONTRAC	- · · · · · · <del>- · · · · · · · · · · · ·</del>	OIANA.	·
SHOW BY DIAGRAM RELATION OF LATERAL	TO WALL OF BUILDING SER		13' K	'DeeP
SIGNED A Vallant	4-9-74 for City	FILED AT ENGIN	EER'S OFFICE	J-9'
		n en		

## **№** 8721

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, Masc	<u>k 12 ,</u>
RECEIVED OF Hamand In	· ·	
FOR WHICH PERMISSION IS GRANTED & Wayne		·
TO TAP Sanitary SE	EWER ON THE Cart	· ·
of 22 and 11 7/ 1/. AVE. T		
THE PREMISES BEING LOT NO. 7239	, House No	3.28
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR 1	1 0-x2	

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.