

✓
N^o 8722

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

3-20-74

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

535

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

4"


WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Estlich

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

J. Nathan 4-9-72
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

LATERAL CEMENTED INSIDE OF BASEMENT

1-10
CUT-OFF
No 8722

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 19

RECEIVED OF Echick Wrecking Co FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED Mrs. Willie Bender

CUT-OFF
TO TAP Sanitary SEWER ON THE South

OF Turner St. S.W. AVE. ST. TYPE OF STREET Hard Surface

THE PREMISES BEING LOT NO. 1698, HOUSE NO. 535

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Echick

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**