

853-1
Nº 8729

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

4-17-74

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

1711

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"


WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

HOLDER BAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



C.O.F.
4'0"

SIGNED

L. Vathum 5-1-74
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair

Nº 8729

OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO,

April 5

RECEIVED OF

Paul J. Sweeney

FEE OF \$ *2.00*

FOR WHICH PERMISSION IS GRANTED

Paul J. Sweeney

TO TAP

Sanitary

SEWER ON THE

West

OF

William Paul E.

AVE.

ST. TYPE OF STREET

East

THE PREMISES BEING LOT NO.

12776

HOUSE NO.

1711

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Halderbaum

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**