

N^o 8730

7-
✓
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

4-10-74

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

1321

SIZE OF PIPE USED

4" C.T.P.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

G. HOLDER BAUM
CLEANOUT

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

V. Nathan

Inspector for City

4-10-74

FILED AT ENGINEER'S OFFICE

JOHNSON ST

REMARKS

SOUTH
BASEMENT WALL CAVED IN WITH SEWER ON SA
SIDE

Repair
N^o 8730

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *April 8*

RECEIVED OF *Haldubrum*

FEE OF \$ *15*

FOR WHICH PERMISSION IS GRANTED *Geo. Putnam*

TO TAP *Sanitary*

SEWER ON THE *West*

OF *Johnson H.S.E.*

AVE.
ST. TYPE OF STREET

Chippewa

THE PREMISES BEING LOT NO. *5447*

HOUSE NO. *1321*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Haldubrum*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**