

N<sup>o</sup> 8732

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED

4-23-74  
UP DOWN

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

wye 10' west of M.H.

HOUSE NO.

822A-822B-824

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

NO

WAS ATTACHED TO MAIN

YES

NAME OF CONTRACTOR

G. HOLDREBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

W  
A

816

822 UP  
822 DOWN

824 UP

6' DP

10'  
2'

SIGNED

V. Vathane

Inspector for City

4-23-74

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8732

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

3-UNITS

MASSILLON, OHIO, April 15

RECEIVED OF Haldubrum FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED William Rice

TO TAP Sanitary SEWER ON THE North

OF William Ave. S.E. AVE. ST. TYPE OF STREET Chapel

THE PREMISES BEING LOT NO. 9716 HOUSE NO. 816

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Haldubrum

**Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.**