✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 8738 AND SIGNED WHEN RETURNED

DATE INSPECTED 5-1-74	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	and a superior of the state of t The state of the state o
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	11 OF BUILDING SERVED.
	ARIVIT HOUSIES ALL Y N N N N N N N N N N N N N
SIGNED	I FILED AT ENGINEER'S OFFICE
Inspector for City	

№ 8738

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,_	affil	16	
RECEIVED OF Benny & parti				
FOR WHICH PERMISSION IS GRANTED FIRST NO.	* I		·	
COT-OFF Santay SE	WER ON THE	Worth		
of A. IV. W. AVE.				
THE PREMISES BEING LOT NO. 13043		/		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR BEAUTY				

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.