## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-1-74	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2116	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 104 EAST OF WH 9 P CURB LINE AND DEPTH
WAS LATERAL AT CURB? YES	
•	NAME OF CONTRACTOR WEAVERSON
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
tana di salah s	The state of the s
	18/2 300 BEND
SIGNED William Jamme	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS	

## Nº 8742

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON,	оню, 21/2	<i>4.13.</i>	
RECEIVED OF MAN DE CAME	2 Louis	Inc.	FEE OF :	s <i>5/2</i>
FOR WHICH PERMISSION IS GRANTED 21/2016		the state of the s		
то тар Замовану	_sewer on the_	<u> </u>	<u> </u>	··
of Margine La W. AVI				
THE PREMISES BEING LOT NO. 1298		, HOUSE NO	3116	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC OF THE DEPARTMENT OF PUBLIC SERVICE.	E NO. 19-1971	DULY PASSED E	BY THE CITY COUNCIL	., AND
NAME OF CONTRACTOR 7	·			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.