## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-16-74	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	· .
HOUSE NO. 1237	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 3 2 4	East of My L'/2's
WAS LATERAL AT CURB? YES	NAME OF CONTRACTOR	HOLDER BAUM
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL		1 /5
SIGNED Cartage	324'	36 300 13-20 5' 26 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
Inspector for City	FILED AT ENGINEER'S	Urrice
REMARKS		

## Nº 8744

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MA	SSILLON, OHIO, 27 44 15		
RECEIVED OF Waldedgerman			
FOR WHICH PERMISSION IS GRANTED LEGAL Pal	Und		
TO TAP Sanitary SEWER	ON THE Marth		
OF Mondand and SE. AVE. TYPE O			
THE PREMISES BEING LOT NO. 5321	. *		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR Holdschum	<del></del>		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.