№ 8761

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 20-1	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	Ranga
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO	WALL OF BUILDING SERVED.
	· ALLOY
,	
	F. 69-6-4
	13 Aca
	12 Parco
SIGNED	FILED AT ENGINEER'S OFFICE
Inspector for C	City FILED AT ENGINEER'S OFFICE
REMARKS	

63 NorTHOS CUT-OF

8761

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON, O	ню, <u>Ремейс Л</u>	جمعي ۽
FOR WHICH PERMISSION IS GRANTED.	Parts Litt	ur.	•
TO-TAP			
	AVE. ST. TYPE OF STREET	yr);	<u>Z</u>
THE PREMISES BEING LOT NO	<u> 218</u> , h	0 10USE NO. 122	· · · · · · · · · · · · · · · · · · ·
WORK TO BE DONE IN ACCORDANCE W	VITH ORDINANCE NO. 19-1971 DL		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.