

3
No 8763

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

DID NOT CUT OFF
CAN'T FIND S.W.E.R

SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Cut off

N^o 8763

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, *June 24*

RECEIVED OF

Beaver Excavating

FEE OF \$

5

FOR WHICH PERMISSION IS GRANTED

Beaver Excavating

TO TAP

Cut off Sanitary

SEWER ON THE

North

OF

Lincoln Way E

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

19554

HOUSE NO.

1206

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Beaver Excavating

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**