## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-15-74	IF SO HOW AND LOCATION FROM 5 TACK INSTACE OF MY WIF
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	6 7 77
A Language	90BENA 49 6'OFF 30 BONA 39 10 BONA 39 10 BONA 39
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	0 P

Meny Nº 8767

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, O	ню, Учену в,	
RECEIVED OF Earl			
FOR WHICH PERMISSION IS GRANTED	<i>A A</i>		
TO TAP Danitary	/ /	<del>-</del>	
OF 14 # 14 21 78.			
THE PREMISES BEING LOT NO. 3832 A HOUSE NO. 17			
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR ACT	Slick	·	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.