Nº 8774

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
House No.	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DGWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	grande (n. 1905). Altitut titak erike erike de serike erike erike erike erike erike erike erike erike erike er Berlinde erike
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WALL	NAME OF CONTRACTOR
-	
u sa	
SIGNED	FILED AT ENGINEER'S OFFICE
Inspector for City	

№ 8774 See*8483

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, July 34
RECEIVED OF 21/4/4044	
FOR WHICH PERMISSION IS GRANTED	<u>. F. adam</u>
TO TAP Samulany SE	
of Ave. St. T	and the second s
THE PREMISES BEING LOT NO. 1124	7 /
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR II Abducto	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.