

✓
N^o 8808

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

1-8-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

23

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

4"

WAS LATERAL AT CURB?

NO

WAS ATTACHED TO MAIN

NO

NAME OF CONTRACTOR

G HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



REPLACED
1-4' PIPE
3' DEEP



2'



20'

Repl.
Ho

SIGNED

[Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair

N^o 8808

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Jan. 6*

RECEIVED OF

Haldenbaum

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

Mrs. B. Ballack

TO TAP

Sanitary

SEWER ON THE

West

OF

14th St. N. W.

AVE.

ST. TYPE OF STREET

City & Sect

THE PREMISES BEING LOT NO.

4241

HOUSE NO.

23

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Haldenbaum

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**