

✓
N^o 8810

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

1-15-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

703

SIZE OF PIPE USED

6" UP

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

4' North of M@W.A.

WAS LATERAL AT CURB?

yes



WAS ATTACHED TO MAIN

NO

NAME OF CONTRACTOR

G. HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

V. Latham
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

REPAIR RELAY

N^o 8810

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, JAN. 9

RECEIVED OF HOLDERBAUM FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

TO TAP SANITARY SEWER ON THE WEST
OF 17TH ST. S.W. AVE. TYPE OF STREET CONCRETE

THE PREMISES BEING LOT NO. 10343, HOUSE NO. 703

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND IN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR HOLDERBAUM

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.