Nº 8812

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 1-21-75	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. ////	DISTANCE EDOM EIDST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT 29 NOTTH OF M 707
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
the second secon	750
N ———	- 1001 A5 note P
	45 7 1
SIGNED V. Vallano	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS	

Nº 8812

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	20
RECEIVED OF A DECEMBER 1	Como Jan .	」 L FEE OF \$. 点ご
FOR WHICH PERMISSION IS GRANTED LEGAL C	,	
TO TAP Santary SEV		
OF 10 H JY. AVE. TY	PE OF STREET This & Sea	2
THE PREMISES BEING LOT NO. 13562	#	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.