FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	SO HOW AND LOCATION FROM RST MANHOLE DOWN STREAM		
HOUSE NO. //20	STANCE FROM FIRST MANHOLE		UPSTroa
SIZE OF PIPE USED	WAN STREAM TO DITCH AT	57 SOUTHO	S M/ 2'0
WAS LATERAL AT CURBY YES	of a second		• 1 <u>2</u> 4.7 · .
WAS ATTACHED TO MAIN	ME OF CONTRACTOR	a, D11)NA
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	F BUILDING SERVED.	8'	1.0
N		7 berg 461	45°
			12'
SIGNED Inspector for City	FILED AT	ENGINEER'S OFFICE	
REMARKS	· .	······································	

Nº 8813

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MA MA	SSILLON, OHIO, JEAC. 10
RECEIVED OF a. A. Crans 4 Sa	
FOR WHICH PERMISSION IS GRANTED Live Live	
	ON THE 6 at
OF 10 th 11 J. V. AVE. TYPE O	
THE PREMISES BEING LOT NO. 13561	\mathscr{A}
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 15	
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR Liana	· · · · · · · · · · · · · · · · · · ·

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.