

N^o 8816

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

1-29-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

123

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?


PROP INSIDE S'

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



SIGNED

J. Salomon

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

CUT-OFF

N^o 8816

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

548

406

142

MASSILLON, OHIO,

Jan 29

RECEIVED OF

Beaman & Son Co.

FEE OF \$

5.

FOR WHICH PERMISSION IS GRANTED

Shelby Street

TO TAP

CUT-OFF
Sanitary

SEWER ON THE

South

OF

East 8th St.

AVE.

ST. TYPE OF STREET

Hard Surface

THE PREMISES BEING LOT NO.

1091

HOUSE NO.

123

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Beaman

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.