$N_{-}^{0} - 8822$

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-21.75		
The state of the s	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 525		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
	CURB LINE AND DEPTH	
WAS LATERAL AT CURB? CGI + OFF		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR OWNER	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
n de la companya de l La companya de la companya de		
	TIDEFA	
	C. L. R. B. Lander	
	OUP STREAM MY	
SIGNED William Cammer	FILED AT ENGINEER'S OFFICE	
inspector to dity		
REMARKS		

№ 8822

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, April 21		
RECEIVED OF And Bammulin	FEE OF \$ 5		
FOR WHICH PERMISSION IS GRANTED La	mmulei		
EUT. OF Flanchaut SE			
of Dale and S. E. AVE. TY			
THE PREMISES BEING LOT NO. 29 24	·		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND			
OF THE DEPARTMENT OF PUBLIC SERVICE.			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.