

No 8828

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED

5-12-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

1041

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

210' EAST OF M/ 8 1/2'

WAS LATERAL AT CURB?

YES


WAS ATTACHED TO MAIN

NO

NAME OF CONTRACTOR

G. MALAVITE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

L. Latham
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 8828

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

April 29

RECEIVED OF

McLain's Excavating

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Drainage

TO TAP

Sanitary

SEWER ON THE

East North

OF

1041 Oak Hill Ave.

AVE.

ST. TYPE OF STREET

Dist.

THE PREMISES BEING LOT NO.

~~13723~~ 13723

HOUSE NO.

1041 Oak Hill

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND IN ACCORDANCE WITH THE ORDINANCES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

McLain's Excavating

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.