

✓
10
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 8841

DATE INSPECTED

9-25-76

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

2345

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

48' EAST OF M 9' DEEP

WAS LATERAL AT CURB?


YES

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

BEAVER

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 8841

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, June 23

RECEIVED OF Paul Kennedy

FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED Paul Kennedy

TO TAP Sanitary

SEWER ON THE South

OF Franklin St. NE

AVE.
ST. TYPE OF STREET City & Hill

THE PREMISES BEING LOT NO. 13576

HOUSE NO. 2345

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND IN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Beaman

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.