FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-15-75 HOUSE NO. 1741	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 11 EAST OF MER 8'D CURB LINE AND DEPTH
WAS LATERAL AT CURB? 5	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DIAMA
SHOW BY DIAGRAM RELATION OF LATERAL TO WALE	L OF BUILDING SERVED.
	L OF BUILDING SERVED.
The second secon	/V
X.	90
SIGNED William Hammer	FILED AT ENGINEER'S OFFICE
Inspector for City	
BELLAND.	

Nº 8844

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, July 7
RECEIVED OF A Acres	Soul Deal FEE OF \$ 23
FOR WHICH PERMISSION IS GRANTED LUMINA	
2.3	SEWER ON THE South
\mathcal{A}	TYPE OF STREET Road Saffine
THE PREMISES BEING LOT NO. 0 4 3 3 3	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE OF THE DEPARTMENT OF PUBLIC SERVICE.	NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I
NAME OF CONTRACTOR MANAGEMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR.	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.