

N^o 8860

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

AND SIGNED WHEN RETURNED

ALSO
S.B 19 P-

DATE INSPECTED

9-16-15

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

241 243

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

96' NORTH OF NH 6'6" DEEP

WAS LATERAL AT CURB?

YES


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

GERSTENLAGER

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

AN



SIGNED

William Hammer

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Duplex
Nº 8860

OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Sept. 15*

RECEIVED OF *Quintanilha*

FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED *Michael Quintanilha*

TO TAP *Sanitary*

SEWER ON THE *W. St.*

OF *21st St. N. W.*

AVE.
ST.

TYPE OF STREET *Chip & Seal*

THE PREMISES BEING LOT NO. *7726*

HOUSE NO. *241-243*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Quintanilha*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**