FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-3/-25 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 15 7 7 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 57 No. 7110 4 111 CX
WAS LATERAL AT GURE?
WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR & Malawite
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
6'P 50'
SIGNED 5 FILED AT ENGINEER'S OFFICE
REMARKS

№ 8867

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

•	MASSILLON, OHIO,	16	
RECEIVED OF MALENTY STATE		FEE OF \$	
FOR WHICH PERMISSION IS GRANTED			
TO TAPSEN		The second secon	
OF AVE. TY	γJ		
THE PREMISES BEING LOT NO. 13551	, HOUSE NO	<u> </u>	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR 2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/	· · · · · · · · · · · · · · · · · · ·		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.