

7.
No 8869

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

3-22-76

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

STURLIN MT 6' DEEP

HOUSE NO.

PASTORS HOME

1219
OVERLOOKS W
DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

No



WAS ATTACHED TO MAIN

Yes

NAME OF CONTRACTOR

G. RICHARDSON & H. ZIMMER

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



311'

SIGNED

V. Kathan

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

LAWN

VIEW Rd TO DORM

C'D

8"

6"

Nº 8869

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Oct 31

RECEIVED OF Genl. P. M. Cunningham FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Manholes Replaced, Temporarily

TO TAP Sanitary SEWER ON THE North

OF Clinton St. E. 21 AVE. ST. TYPE OF STREET Blk. 100

THE PREMISES BEING LOT NO. 01-100, HOUSE NO. 1219 - Duval St. Ave.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Deane

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.