

N<sup>o</sup> 8876

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED

11-11-75

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO.

7323

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

186' East of M/H 11

WAS LATERAL AT CURB?

Yes


WAS ATTACHED TO MAIN

NO

NAME OF CONTRACTOR

Crest

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

J. L. Scham  
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8876

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

MASSILLON, OHIO, Nov. 5

RECEIVED OF Crest Excavating FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED Rain - Rupture

TO TAP Sanitary SEWER ON THE North

OF Rand Rd N.E. AVE. ST. TYPE OF STREET Chip & Seal

THE PREMISES BEING LOT NO. 11670, HOUSE NO. 1323

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND IN  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Crest

**Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.**