## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-21-75 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM.			
House No. 1333			
SIZE OF PIPE USED 6 DOWN STREAM TO DITCH AT 382 EAS TOF M 8'D			
SIZE OF PIPE USED. CURB LINE AND DEPTH J 8 4 5 1 0 1 77 8 4			
WAS LATERAL AT CURB? YE'S			
WAS ATTACHED TO MAIN NAME OF CONTRACTOR CREST			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
300 BENG			
1/5			
N = 382'			
SIGNED William Hammer FILED AT ENGINEER'S OFFICE			
Inspector for City			
to provide the control of the figure of the control			
REMARKS			

**№** 8877

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO,	How. 5
RECEIVED OF CAUT Coxcava		FEE OF \$ 25
FOR WHICH PERMISSION IS GRANTED Saieu	- Hustine	·
TO TAP Sainting SE		
OF Bud an. n. E. AVE. T.	YPE OF STREET G	lip & Sul
THE PREMISES BEING LOT NO. 11669		<b>/</b> *
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	NO. 19-1971 DULY PAS	SED BY THE CITY COUNCIL, AND I
NAME OF CONTRACTOR Cust		· -
•		•

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.