

N^o 8891

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

12-29-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

437

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

4"

WAS LATERAL AT CURB?

IN PROP

YES

WAS ATTACHED TO MAIN


NO

NAME OF CONTRACTOR


G. HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

— A — N



UPPER 4" SEWER
CUTOFF



SIDEWALK

SIGNED

J. V. [Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Found Pipe Broke & a 3/4" Pipe inside 2' LONG
Plus Roots
Replaced 4' of 4" Pipe

Repair

Nº 8891

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO,

Dec. 26

RECEIVED OF

Halderbaum

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

Jack Barnett

TO TAP

Sanitary

SEWER ON THE

West

OF

17th S.W.

AVE.

ST. TYPE OF STREET

City & local

THE PREMISES BEING LOT NO.

5067

HOUSE NO.

437

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND F
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Halderbaum

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**