## Nº 8901 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED /-20-76 HOUSE NO. 514                            | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  |
|---|--|
| SIZE OF PIPE USED   | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH  |
| WAS LATERAL AT CURB?  |  |
| WAS ATTACHED TO MAIN  | NAME OF CONTRACTOR   |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. |  |
|   | The second secon |
| N/  | 60'  |
| IV .  |  |
| · ·   |  |
| SIGNEDInspector for City  | FILED AT ENGINEER'S OFFICE   |
| Inspector for City  |  |
| REMARKS   |  |

**№** 8901

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

| MASSILLON, OHIO, 16   |
|---|
| RECEIVED OF LALLE A Jollins Co. FEE OF \$ 5.  |
| FOR WHICH PERMISSION IS GRANTED THE LEAVE LEAVE LEVEL   |
| COT OF F Sauctury SEWER ON THE East   |
| OF 3 de 11 16 AVE. TYPE OF STREET 16 6 LINGULE  |
| THE PREMISES BEING LOT NO. 2896 , HOUSE NO. 5/4   |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I |
| NAME OF CONTRACTOR  |
| $\mathcal{A}\mathcal{B}$  |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.