

N^o 8928

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

June 17 - 76

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

2043

SIZE OF PIPE USED

6

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

10 Feet Back of curb


WAS ATTACHED TO MAIN

yes

NAME OF CONTRACTOR

Griss Bros

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8928

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *April 27*

RECEIVED OF *Erving Bros.*

FEE OF \$ *35.*

FOR WHICH PERMISSION IS GRANTED *Erving Bros.*

TO TAP *Sanitary*

SEWER ON THE *South*

OF *Ironwood Cir 71.6*

AVE.

ST. TYPE OF STREET *City of Mass*

THE PREMISES BEING LOT NO. *13735*

HOUSE NO. *2043*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *W. Melanite*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.