## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

 $N^{\underline{0}}$ 

8936

DATE INSPECTED May 13,19	76 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO.		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
<i>(3</i> )	lool at Barnet	
•		
SIGNED May 13 Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

CUT-0FF Nº 8936 ✓

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON,	оню, /// а.у	/ /3
RECEIVED OF BLANCE &	institute Co		FEE OF \$
FOR WHICH PERMISSION IS GRANTED SHOULD	Led Telypoon	e Co.	
A ST A DE G	sewer on the	m_	-
OF 0 20 11 16			Li. general
THE PREMISES BEING LOT NO. //3/			
WORK TO BE DONE IN ACCORDANCE WITH ORDIN			•
OF THE DEPARTMENT OF PUBLIC SERVICE.			
and the second of the second o			the state of the s

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.