FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

8940

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
0000	ed affect Besmont
Programme and the second	
SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

eur-0=
Nº 8940

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

M	ASSILLON, OHIO, 771 a4	17
RECEIVED OF East 30 Wincking	g V	FEF DE S
Reenard .	Herving	· · · · · · · · · · · · · · ·
CNT. UFF Samulary SEWER	ON THE East	·
OF 4 S.W. AVE.	CFSTREET (Mits F)	Lil
THE PREMISES BEING LOT NO. 4132	i	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 1	9-1971 DULY PASSED BY THE	CITY COUNCIL, AND F
NAME OF CONTRACTOR East 30		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.