FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 10' fut pessel	
WAS ATTACHED TO MAIN JA	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	OF BUILDING SERVED.
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	of north good house star of the sent such of the book an infect behind our to have up
SIGNED V	FILED AT ENGINEER'S OFFICE
Inspector for City	

Nº 8944

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

nd . . -

	MASSILLON, C	OHIO, 1/144	23
RECEIVED OF LANGE B	lav.		FEE OF \$ 35
FOR WHICH PERMISSION IS GRANTED	ien Bear	J .	
	SEWER ON THE		
of Oakhill Dr. 11.6.			
THE PREMISES BEING LOT NO. 13749	, !	/ HOUSE NO	918
WORK TO BE DONE IN ACCORDANCE WITH ORDINAN		JLY PASSED BY THE	CITY COUNCIL, AND F
NAME OF CONTRACTOR MELANITE		****	
			**

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.