

✓
Nº 8954

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED Oct- 77

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 912

SIZE OF PIPE USED 6


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Repair

WAS ATTACHED TO MAIN Repair

NAME OF CONTRACTOR Holden Bum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED JHL
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair

N^o 8954

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

June 16

RECEIVED OF

Halderbaum

FEE OF \$

25.

FOR WHICH PERMISSION IS GRANTED

Mrs. E. Jackson

TO TAP

Sanitary

SEWER ON THE

North

OF

North

AVE.

ST. TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

958

HOUSE NO.

912

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND F
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Halderbaum

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.

Web. A. M.