

N^o 8962

✓
 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
 AND SIGNED WHEN RETURNED

DATE INSPECTED July 30, 76IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMHOUSE NO. 2523SIZE OF PIPE USED 6DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH3.5 ftWAS LATERAL AT CURB? yesWAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Empty lot32 feet 6" pipe7 feet deep15 feet behind wallReynolds Bros

SIGNED

H. J.
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8962

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *July 29*

RECEIVED OF *Paul Kanovsky*

FOR \$ *25.*

FOR WHICH PERMISSION IS GRANTED *Paul Kanovsky*

TO TAP *Sanitary*

SEWER ON THE *South*

OF *Valleywood Ave. N.E.*

AVE.

ST. TYPE OF STREET *City & Loc*

THE PREMISES BEING LOT NO. *13671*

HOUSE NO. *1583*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND BY THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Beaman*

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.