№ 8991

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	
Did not call in &	liver in it much
No recarde	
•	
SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE
inspector for City	
REMARKS	

√º 8991

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO,	Syl. 78
RECEIVED OF Structure De	nelofment, Ler	e FEE OF \$ 25:
OR WHICH PERMISSION IS GRANTED AND	in Warethe	· · · · · · · · · · · · · · · · · · ·
O TAB Sanitary	SEWER ON THE	South
Vallyword and no. 71. E.		Chip & lead
HE PREMISES BEING LOT NO. 13672	, Hous	1533
WORK TO BE DONE IN ACCORDANCE WITH ORD	INANCE NO 10 1071 DILLY	DASSED BY THE CITY COUNCIL AND B

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malawite

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.