Nº 9014

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
	HOUSE NO	DISTANCE FROM FIRST MANUALS
	SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
	WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN NAME OF CONTRACTORSHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		

SIGNED______ FILED AT ENGINEER'S OFFICE______

EMAKKS

Nº 9014

OFFICE OF THE DIRECTOR OF PUBLIC SERVER

	MASSILLON, OHIO, DEC	
RECEIVED OF Gail 30 6 Kcane	ling	FEE OF \$5,00
FOR WHICH PERMISSION IS GRANTED Scatt & A	Lewitt	
A.UT.OFF A .A	ــــــــــــــــــــــــــــــــــــــ	
CUT. OFF JETULING SE	NER ON THE WWW.	
OF Chuland St. J. VV. AVE. TY.		
THE PREMISES BEING LOT NO. 4148	, HOUSE NO. /3	15
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO		
OF THE DEPARTMENT OF PUBLIC SERVICE.		
Est 30		

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.