Nº 9025

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED Thus 20 7 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO
SIZE OF PIPE USED
WAS LATERAL AT CURB?
WAS ATTACHED TO MAIN The NAME OF CONTRACTOR Maly to
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
Thethop 20 feet from Southwest corner
Show by diagram relation of Lateral to Wall of Building served. The deep 20 feet from Southwest Corner Corne
SIGNED 247 cal hill FILED AT ENGINEER'S OFFICE
Inspector for City

Nº 9025

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, Maich 3
RECEIVED OF GUILLY BUS.	Que. FEE OF \$25.
FOR WHICH PERMISSION IS GRANTED	
TO TAP Sanitary S OF Cachiel In 116 AVE. ST.	TYPE OF STREET Chind had
THE PREMISES BEING LOT NO. 13718	, HOUSE NO
	NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RI
NAME OF CONTRACTOR MALE VILLE	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.