

Nº 9033

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

House torn down plugged at basement

SIGNED _____

John Lewis
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Cut-off

N^o 9033

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

April 1

RECEIVED OF

East 30 Excavating

FEE OF \$5.⁰⁰

FOR WHICH PERMISSION IS GRANTED

Rejo

CUT-OFF

TO TAP

Sanitary

SEWER ON THE

West

OF

1st St. S.E.

AVE.

ST. TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

2024

, HOUSE NO.

423

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTION NO. 19-1971 OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

East 30

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.